

Bore Gauge

▶ Reading 0.01 mm


Model name	S-0,01	L-0,01
Reading	0.01 mm	0.01 mm
Range per revolution	1 mm	1 mm
Contact surface	Ø 7,7 mm	Ø 29 mm
Range	Ø 0.5 mm to Ø 3.5 mm	Ø 3 mm to Ø 6 mm

Bore Gauge


▶ Reading 0.001 mm

Model name	S-0,001	L-0,001
Reading	0.001 mm	0.001 mm
Range per revolution	0,1 mm	0,1 mm
Contact surface	Ø 7,7 mm	Ø 29 mm
Range	Ø 0.5 mm to Ø 3.5 mm	Ø 3 mm to Ø 6 mm


Schematic illustration of the Bore Gauges:




S-0,01



L-0,01



S-0,001



L-0,001