












Measuring Inserts M2.5

Measuring inserts with thread M2.5		
1003312 TN10W		
1003315 Tip with ruby ball		
1003313 Tip with PEEK ball		
1002450 TN12		
1002452 TN20		
1002454 TN30W		
1002456 TN70		